

High & Mighty Remover

Heavy-Duty Coating Stripper

This incredible, very low-odor remover is intended for use on extremely difficult to remove coatings; designed specifically for Urethane and Acrylic floor finishes. It is safe for use on VCT tile surfaces. It will not yellow the tile surface when used properly.

Instructions:

1. SHAKE or STIR WELL BEFORE USING.
2. Pour *High & Mighty Remover* onto desired surface. Always test High & Mighty Remover in a small and inconspicuous place to ensure that the flooring surface does not get damaged.
3. With a V-Notched 15-25 mil squeegee; distribute the stripper evenly across the desired area, avoid working the product vigorously. *High & Mighty Remover* may also be applied with a paint brush or paint roller.
4. Allow the *High & Mighty Remover* to stand on the surface for a minimum of 20 minutes or until the coating begins to wrinkle.
5. Combine 1 part *High & Mighty Cleaner Concentrate* with 3 parts water (25%) into solution tank of machine scrubber (cylindrical brush or circular roto).
6. After 20 minute dwell time, begin scrubbing the floor with the machine scrubber while simultaneously releasing a generous amount of the cleaning solution.
7. Remove stripped coating with a wet vacuum. Dispose of stripped coating in compliance with local laws and regulations.
8. Flood-mop the floor with Citric Acid & water solution and scrub the floor with the machine to neutralize the floor.
9. Wet-vacuum the floor and rinse it with water numerous times
10. Allow floor to dry thoroughly before re-application of High & Mighty. Also confirm that the pH of the floor is Neutral (7.0) before applying High & Mighty.